

Public TL 9000 Registration Profile

TL5443 - TL 9000 Registration Public Profile

Certification Status	Certified
Certificate Number	15/12T6311R2M
Date First Certified to TL 9000	2006-12-28
Current Certification Date	2012-10-17
Certificate valid until	2015-10-16
Company Name	Hangzhou Eastcom Software Technology Co. Ltd.
Registration Organization Name	Hangzhou Eastcom Software Technology Co. Ltd.
Primary Registration Administrator	Rosa Shi
Alternate Registration Administrator	Xiaolan Zhang

Registration ISO Status	ISO 9001:2008
Registration Option	TL 9000-S
Exemptions	
Requirements Release	R5.0
Measurements Release	R4.5
NACE Code H	None
NACE Code S	K 72.2
NACE Code V	None
ISO 9001 Scope	Design, Development, Implementation and Technical Support of Operation Support System & Business Service Management Software
TL 9000 Scope	Design, Development, Implementation and Technical Support of Operation Support System & Business Service Management Software
Registrar Company Name	WIT Assessment Co., Ltd.
Accreditation Body	10648

Locations

Facility Name	Address	City	State/Province	Country/ Region	Zip/Postal Code
Eastcom Building	No.398 Wensan Road, Xihu District	Hangzhou	Zhejiang	China	310012



Product Category

Product Category	Description
4.2.1	On-line Critical Operations Support Systems

Requirement Exclusion

Requirement Release	Adder No	Description	Date First Certified
No Exclusions			

Measurements Exemption

Product Category ID	Measurement List	Date First Certified
No Exemptions		

Registration Information

Company Name	Hangzhou Eastcom Software Technology Co. Ltd. 8th Floor, Eastcom Building, 398# Wensan Road Hangzhou,Zhejiang China Phone:86-571-88865183 URL:http://www.eastcom-sw.com
Registrar Company Name	WIT Assessment Co., Ltd. 17~18th Hengxin Building NO 588 Jiangnan Avenue, Binjiang District Hangzhou,PRC China Phone:008657187711611 URL:http://www.wit-int.com

Contact Information

Primary Registration Administrator	Rosa Shi 9th Floor, Eastcom Building, 398# Wensan Road Hangzhou Hangzhou,Zhejiang China Phone:86-571-88865251 Email:shirong@eastcom-sw.com



Alternate Registration Administrator	Xiaolan Zhang No.398 Wensan Road China Phone:0571-88865251 Email:sunnyzhang@eastcom-sw.com